

Baseball Annex

Building Coordinator: PJ Finigan

Building Background:

- Two Floors
- Fire extinguisher locations:
 - Both lower-level staircase exits
 - First floor near maintenance closet
 - First floor outside men's restroom
- Fire alarm locations:
 - Next to sprinkler room on first level

Building Evacuation Route: In the event of severe weather, all building occupants should seek shelter in the lowest part of the building. If unable to get to the shelter area, seek a windowless room or hallway on the first floor of the building.

Evacuation Assembly Area:

- Parking lot closest to Karen Street

Bad Weather/Safe Area: In the event of severe weather, all building occupants should seek shelter in the lowest part of the building. If unable to get to the shelter area, seek a windowless room or hallway on the first floor of the building.

LU Security: 24/7 – (636) 949-4911